

INSTRUCTIONS - Tether Attachment for the BDX Series Moisture

Meter

Each meter includes two short pieces of nylon cord to tie into tethers for the pin and connector caps, if desired.

Step 1 – Remove the connector cap.



Step 2 – Thread one end of the Tether through the cavity of the meter.



Step 3 – Feed both ends through the top side of the connector cap.



Step 4 – Tie a single knot on the end of the Tether.



Step 5 – Slide the connector cap to the end so that the knot is inside and place the cap back onto the meter as shown.



Step 6 – Remove the Pin Cover Cap and repeat the same steps.



Rev. 6-16-2021-1