



## Dock Ladders Recalled by CMP Group

### Ladders post a laceration hazard

CMP Group has issued a recall of their dock ladders due to sharp edges on the side of the steps. These edges pose a laceration hazard to the user. Consumers should immediately stop using these ladders and contact CMP Group to return the ladder. Consumers will be issued a full refund or a replacement ladder.

The recall involves silver aluminum standoff and wide step ladders sold in three sizes; three steps, four steps and, five steps. The ladders involved include the following models and UPC numbers:

- Model DE2053F 3 and UPC 776113205303
- Model DE2054F 4 and UPC 776113205402
- Model DE2055F 5 and UPC 77611320550
- Model DE2043F 3 and UPC 776113204306
- Model DE2044F 4 and UPC 776113204405
- Model DE2045F 5 and UPC 776113204504

The standoff ladders were sold online at Amazon.com and at Boat Hoist, CWR Electronics, and Global Industrial Distribution from September 2017 through July 2020. The wide step ladders were sold online at Amazon.com and at CWR Electronics and Global Industrial Distribution from June 2019 through July 2020. The recalled ladders sold for between \$150 and \$250.

Additional information may be obtained by visited the CPSC website by clicking the link below.

<https://www.cpsc.gov/Recalls/2020/CMP-Group-Recalls-Dock-Ladders-Due-to-Laceration-Hazard>

As always, if you have any questions or need additional assistance, please contact your ORCIG Safety Specialist.



# RecallALERT<sup>SM</sup>



ORCIG 2020 RecallAlert Series

This material is intended to be a broad overview of the subject matter and is provided for informational purposes only. Old Republic Contractors Insurance Group, Inc. does not endorse or recommend any products or services nor does it make any representation or warranty regarding the accuracy or completeness of the information. Old Republic Contractors Insurance Group, Inc. shall have no liability or responsibility to any person or entity with respect to any loss, action or inaction alleged to be caused directly or indirectly as a result of the information contained herein.

