



Yeti Recalls Rambler Travel Mugs

The lid can fail and eject hot liquids

On November 4, 2020, Yeti issued a recall for approximately 241,500 Rambler™ 20 oz. Travel Mugs with Stronghold Lids. According to Yeti, the lid's MagSlider™ and mug contents can be expelled if the mug is filled with hot liquid, sealed with the lid, and agitated or inverted, which can pose a burn hazard. The United States Consumer Product Safety Commission (CPSC) provided the following pictures of one the several colors of mugs impacted by this recall.



For more information regarding this recall and how to identify a defective mug please click on the links below:

- <https://www.cpsc.gov/Recalls/2021/YETI-Recalls-Rambler-Travel-Mugs-with-Stronghold-Lid-Due-to-Injury-and-Burn-Hazards#>
- https://www.yeti.com/en_US/product-recall.html

RecallALERTSM



ORCIG 2020 RecallAlert Series

This material is intended to be a broad overview of the subject matter and is provided for informational purposes only. Old Republic Contractors Insurance Group, Inc. does not endorse or recommend any products or services nor does it make any representation or warranty regarding the accuracy or completeness of the information. Old Republic Contractors Insurance Group, Inc. shall have no liability or responsibility to any person or entity with respect to any loss, action or inaction alleged to be caused directly or indirectly as a result of the information contained herein.

