

PF2200 Dual Burner BMS Software Release Notes

Updated:

March 30, 2020

PROFIRE Contacts:

solutions@profireenergy.com



Purpose of Document

This document is meant to provide customers with a list of changes for each software bundle release. The notes are categorized by their software bundle release version (e.g. AA-B.C.D). Where:

- AA: Product Variant Type (e.g. SB Single Burner)
- B: Major Software Release (typically with new features)
- C: Minor Software Release (typically with fixes / changes)
- D: Build Number (internal use only)

Modification to software is generally split up into three main categories:

- NEW: Software modifications that add additional functionality (e.g. features).
- CHANGES: Software modifications which modify existing behavior.
- FIXES: Software modifications which correct identified issues (e.g. bugs).

Known Safety Issues

Description	Work Around	Affected Version(s)	Fixed Version
In weakly grounded systems, excessive sparking may cause phantom key presses and/or board resets.	Ensure proper grounding. Avoid excessive sparking in weakly grounded systems (eg. Use a standing pilot, dial back the gas pressure).	DB-1.0.3	N/A



List of Software Releases

DB-1.0.3	4
Version History	5



DB-1.0.3

DB-1.0.3 was released Mar 30, 2020 and is the first major release of the Dual Burner product variant. This release is for Field Trial purposes ONLY.

NEW:

> Initial release

CHANGES:

> Initial release

FIXES:

> Initial release



Version History

Document Version	Date	Description of Changes	
v1.0	Mar 30, 2020	Initial document release (linked to DB 1.0.3 bundle	
		release).	