

Diameter (mm)	minimum depth (mm)	max depth (mm)
4	5	15
5	5	15
6	5	20
8	5	25
10	5	30
from 12 to 19,9 with decimal steps	5	35
from 20 to 39,9 with decimal steps	5	40
from 40 to 49,9 with decimal steps	5	60
from 50 to 120 with decimal steps	5	80