



## ***Lochinvar Recalls Condensing Residential Boilers***

**Recall Date: June 18, 2020**

**Recall number: 20-141**

### **Hazard:**

Deterioration of the flue grommet on several models can lead to carbon monoxide gas leaks. Carbon monoxide is a highly toxic, colorless, odorless gas produced by burning fuel, which can lead to severe illness or death in certain concentrations.

### **Remedy:**

Homeowner's are advised not to use the boilers, and to contact the installer or a qualified technician immediately to perform a free repair. Those who must use their systems before they can be repaired are urged to ensure that working carbon monoxide alarms are installed throughout the their home.

The recall includes several Lochinvar, A.O. Smith, and State Proline brand residential condensing boilers, combi boilers, and packaged systems sold after August of 2016. Lochinvar received several reports of the issue, including two injuries from carbon monoxide poisoning.



For more information visit <https://www.waterheaterrecall.com/>, view the [recall notice](#) published by the [US Consumer Product Safety Commission](#), or contact [Lochinvar](#) toll free at: 833-232-9706.

# RecallALERT<sup>SM</sup>



ORCIG 2020 RecallAlert Series

This material is intended to be a broad overview of the subject matter and is provided for informational purposes only. Old Republic Contractors Insurance Group, Inc. does not endorse or recommend any products or services nor does it make any representation or warranty regarding the accuracy or completeness of the information. Old Republic Contractors Insurance Group, Inc. shall have no liability or responsibility to any person or entity with respect to any loss, action or inaction alleged to be caused directly or indirectly as a result of the information contained herein.

