

# INFRA Protokoll: Trondheimsveien 619 øst

**Kund:** Franzefoss Pukk AS  
Olav Ingstads vei 5  
Postboks 53  
1309 RUD

**Prosjekt:**

**Kund Kontakt:** Tom Paulsen

**Telefon:** 97051404

**Kolumn 1**      **C10-6118-1 Bånkall - GEO**

**Kolumn 2**

**Kolumn 3**

**Kolumn 4**

---

**Från:**            **21.04.2020 00:00:00**

**Till:**             **22.04.2020 23:59:59**

---

**Noteringar:**

**Konsult:**        Pål Jørgen Streitlien  
99589783

---

**Nexconsult AS**

Adress: Kobbervikdalen 75, 3036 Drammen

WEBB: [www.nexconsult.no](http://www.nexconsult.no)

VAT. no.: 991 968 334

Telefon: +4732826870

Fax: +4732826871

E-post: [post@austin.no](mailto:post@austin.no)

**Projekt:**

<b>Kolumn</b>	<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>
Punkt:	C10-6118-1			
Master:	6118			
Sensor-id:	C10-6118-1	--	--	--
Kalibrerad:	28.02.2019			
Standard:	NS8141 Byggverk 250 mm/s 5-300Hz			
Intervalltid:	2 minuter			
Storhet:	Velocity			
Enhet:	mm/s			
Övre tröskel:	0,5			
Undre tröskel:	N/A			

<b>Datum/Tid</b>	<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>
21.04.2020 13:57:42	REGON			
22.04.2020 14:02:00	1,25			
22.04.2020 14:58:00	REGOFF			