

**ASSET COMPLIANCE & VERIFICATION SOFTWARE** 

## JACKAL CREEK GOLF ESTATE CASE STUDY

#### **PROJECT**

Verification & Compliance – Golf Carts & Course Maintenance

#### **SECTOR**

Recreational

#### DATE

Engagement - Nov 2019


#### **HOW DID ASSETPOOL HELP?**

Jackal Creek recently purchased around 70 new Golf Carts with builtin course GPS management. Their previous fleet had to be replaced due to the condition of the carts. AssetPool checks the carts out in the morning and check the carts on return. If the player has caused damage to the cart the club is now able to recover these costs.

Furthermore there was a need for better record keeping of course maintenance and compliance. The clubs management can now without a doubt ensure that their course is being attended to by the green keeper and his staff as required.

#### **KEY BENIFITS**

- Golf Cart physical condition verification & monitoring
- · Golf course maintenance management
- Staff efficiency & performance management
- Paperless record keeping Immediate data access



## **HOLE 1 – Course Inspection**

### GOLF CART – Daily Inspection Job Report



Jackal Creek Golf Estat Boundary Roa North Riding AH, Roodepool Gauten South Africa, 216

Registration No: 1999/023112/0 VAT No: 414021263







VAT No: 4140212633

# **Started:** Thu, Dec 19, 2019 3:12 AM Completed: Thu, Dec 19, 2019 3:15 AM





Zandevco (Pty) Ltd - Jackal Cree Boundary R Jackal Creek Golf Estate, Roodepoor Gauten South Africa, 216 Registration No: 1999/023112/0 VAT No: 414021263

#94 GOLF CART DAILY INSPECTION			Failed Overall Outcome
Internal Asset ID Cart 26 Performed by Nicholas Gillans started at Thu, Dec 19, 2019 4:17 AM completed at Thu, Dec 19, 2019 4:18 AM	Golf Carts Golf Cart Checklist - End of Day- Daily	Medium Risk Level	<b>Passed</b> Outcome
#5928 - GPS Is the golf cart GPS working?			Ok 🥝
85929 - Tyres Check all tyres for any damages			Ok 🥝
#85930 - Windscreen Clean Is the windscreen clean?			Ok 🥝
#5931 - Bodywork Damage Front and Rear Inspect the cart for any bodywork damage - Front & Rear			Ok 🥝
#85941 - Bodywork Damage - sides Bodywork Damage - Left Side & Right Side			Ok 🥝
#5992 - Bag-Straps Check for bag straps			Ok 🥝
## ## ## ## ## ## ## ## ## ## ## ## ##			Ok 🥝
#5934 - Sand Bottle Full Is the sand bottle filled?			Ok 🥝
#5935 - Cooler Box Clean Is the cooler box clean?			Ok 🥝
#5936 - Cart Cleaned Is the golf cart clean?			Ok 🥝
#5937 - Cart Charged			Ok 🔗

#### **#93** GOLF COURSE INSPECTION





Internal Asset # Hole 1		
Performed by Sidney Hart on Thu, Dec 19, 2019	Hole 1	Hig
3:12 AM	Hole Inspection Checks	Risk Leve

1. Verify Yellow Tees

Check the Tees are in place, the grass has been cut , that the Tee Box has been moved recently and that the yellow distance marker is trimmed and clearly visible



, which is a second of the sec	
2. Verify White Tees	
Check the Tees are in place, the grass has been cut, that the Tee Box has been moved recently, and that the white distance marker is trimmed and clearly visible	Ok ⊗
3. Verify Blue Tees	
Check the Tees are in place, the grass has been cut, that the Tee Box has been moved recently and that the blue distance marker is trimmed and clearly visible	Ok ⊘
4. Verify Red Tees	
Check the Tees are in place, the grass has been cut, that the Tee Box has been moved recently and that the red distance marker is trimmed and clearly visible	Ok ⊘
5. Fairway condition	
Fairways cut, any bare patches, bad ride-on areas.	Ok ⊘
6. Sprinklers	
Have they been edged. Any broken or leaking sprinklers	Ok⊗
7. Semi Rough	
please check Cut and definition	Ok ⊘
8. Bunkers - Fairway	
Check bunker is in good condition	Ok ⊘

