



ASSETPOOL

ASSET COMPLIANCE & VERIFICATION SOFTWARE




Unit G4 Pinelands Office Park
Maxwell Drive
Modderfontein, Lethabong
Gauteng
South Africa, 1645
Registration No: ck 1997/001837/23
VAT No: 4320163167

CONFIDENTIAL

#257 VEHICLE INSPECTION &
BRAKE TEST

Passed
Overall Outcome



Asset: [redacted]
Performed by [redacted] on Wed, Oct 9, 2019
2:24 PM

[redacted] Front End Loader

Critical
Risk Level
Passed
Outcome

1. Operator Authorisation Card
Check if valid Check expiry date

Ok

2019 © AssetPool (Pty) Ltd. All Rights Reserved • assetpool.co • Generated Wed, Oct 9, 2019 7:35 PM

Page 1 of 6

THE INCIDENT – PLATINUM MINE NW PROVINCE SOUTH AFRICA (9TH OCTOBER 2019 – 19H00)

The front-end loader, seen in the image below, rolled down an embankment damaging the loader and injuring the driver. In events like these the DMR “Department of Mineral Resources” must be notified and evidence must be given immediately proving that the machine and operator were cleared to work. In the event where this evidence cannot be provided the Mine may be shut down at a substantial cost to the Mine.

HOW DID ASSETPOOL HELP?

- Inspection history on the machine was provided within minutes due to AssetPool’s cloud hosted AWS platform
- The latest inspection was done at 14h24 that same day
- There was no downtime, AssetPool proved compliance
- We could prove, “WHEN” the machine and operator were inspected
- We could prove, “WHERE” the machine was when inspected
- We could prove, “WHAT” machine it was due to the unique identifying QR code on the machine
- We could prove, “WHO” checked & verified compliance



assetpool.co